



PLEASE PRINT OR TYPE

(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

**UNIFORM HAZARDOUS
WASTE MANIFEST**

1. Generator's US EPA ID No.
I.A.D.O.O.O.2.2.2.6.5.3

Manifest
Document No.
M.3.

2. Page 1
of 1

Information in the shaded areas is
not required by Federal law, but
items D, F, H and I are required by
State law.

3. Generator's Name and Mailing Address

**Climax Molybdenum Co.
Hwy 61 South
Fort Madison, Iowa 52627**

4. Generator's Phone (**319**) **463-7151**

5. Transporter 1 Company Name

Heritage Transport

7. Transporter 2 Company Name

6. Use EPA ID Number

I.N.D.O.5.8.4.8.4.1.1.4

8. Use EPA ID Number

I.N.D.O.9.3.2.1.9.0.1.2

9. Designated Facility Name and Site Address

**Heritage Environmental Services
7901 West Morris St.
Indianapolis, Ind. 46231**

10. Use EPA ID Number

I.N.D.O.9.3.2.1.9.0.1.2

A. State Manifest Document Number

INA 0273589

B. State Generator's ID

C. State Transporter's ID

D. Transporter's Phone **317/241-9406**

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID

H. Facility's Phone

317/243-0811

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

**RO, Hazardous Waste Solid
ORME-E, NA9189, (EPA-EPTTOXI)**

12. Containers

No. Type

13.
Total
Quantity

14.
Unit
Wt/Vol.

I.
Waste No.

1 T T

15

T

D004

RCRA 09/13/1988



347

J. Additional Descriptions for Materials Listed Above

**Molybdenum Sulfide Cake, Exempt
from RCRA by paragraph, 261.4**

K. Handling Codes for Wastes Listed Above

D004

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Thomas E. Anderson

Signature

Thomas E. Anderson

Month **9** Date **13** Year **88**

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Clyde Bunch

Signature

Clyde Bunch

Month **09** Date **13** Year **88**

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month **.** Date **.** Year **.**

19. Discrepancy Indication Space

RECEIVED

RECEIVED

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted Item 19.

Printed/Typed Name

Thomas E. Anderson

Signature

Thomas E. Anderson

Month **.** Date **.** Year **.**

IOWA SECTION

COPY 2: GENERATOR MAIL TO GENERATOR STATE

In case of a spill call the Indiana Office of Environmental Response at 317/241-4336 (day or night) and the National Response Center at 800/424-8802 or 202/426-2675.

INA 0273589

When using the uniform waste manifest for rail or water (bulk shipments) or international shipments, refer to the applicable State regulations.

INSTRUCTIONS TO GENERATORS (Please type or print clearly)

- (1) Enter **generator's** U.S. EPA twelve digit identification number and the unique five digit document number assigned to this Manifest (e.g., 00001) by the generator.
- (2) Enter total number of pages comprising this Manifest.
- (3) Enter **generator's** name and mailing address.
- (4) Enter telephone number where an authorized agent of the **generator** may be reached in event of an emergency.
- (5, 6) Enter company name and U.S. EPA I.D. number of the first **transporter** who will transport the waste.
- (7, 8) If applicable, enter company name and U.S. EPA I.D. number of the second **transporter** who will transport the waste. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA Form 8700-22A).
- (9, 10) Enter company name, **site** address, and U.S. EPA I.D. number of the **facility** designated to receive the waste listed on this Manifest.
- (11) Enter U.S. DOT Proper Shipping Name, Hazard Class, and I.D. number (UN/NA) for each waste as identified in 49 CFR 171 through 177. Note: If additional space is needed for waste descriptions, enter in Item 28 on the Continuation Sheet (EPA Form 8700-22A).
- (12) Enter number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I - Types of Containers

DM—Metal drums	TT—Tank Trucks	CM—Metal boxes (including roll-offs)
DW—Wooden drums	TC—Tank cars	CW—Wooden boxes
DF—Fiberboard/plastic	DT—Dump truck	CF—Fiber or plastic boxes
TP—Tanks portable	CY—Cylinders	BA—Bags

- (13) Enter total quantity of waste described on each line.
- (14) Enter appropriate abbreviation from Table II (below) for the unit of measure.

Table II - Units of Measure

P = Pounds	L = Liters (liquids only)
K = Kilograms	G = Gallons (liquids only)
Y = Cubic yards	T = Tons (2,000 lbs.)
N = Cubic meters	M = Metric tons (1,000 kg.)

- (16) The **generator** must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below.

THE FOLLOWING INFORMATION IN THE SHADED AREAS IS REQUIRED BY INDIANA STATE LAW

- (D) Enter the phone number of **first transporter**.
- (F) Enter the phone number of **second transporter** (if applicable).
- (H) Enter the phone number of the designated facility.
- (I) Enter the most appropriate EPA waste code.

GENERATOR IN STATE: Retain **Copy 8** and detach and mail **Copy 2** to Indiana D.E.M.

GENERATOR OUT OF STATE: Retain **Copy 8** and mail **Copy 2** to the Generator State (if applicable) and mail **Copy 3** to Indiana D.E.M.

INSTRUCTIONS TO TRANSPORTERS (Please type or print clearly)

- (17, 18) Enter name of the person accepting the waste on behalf of the **transporter**. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

TRANSPORTER(S): Retain **Copy 7 (Copy 6)** and leave remaining copies with **FACILITY OWNER/OPERATOR**.

INSTRUCTIONS TO OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES (Please type or print clearly)

- (19) The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any discrepancy between the waste described on the Manifest and the waste actually received at the facility.
- (20) Print or type name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

OWNER/OPERATOR IN STATE: Retain **Copy 5**, return **Copy 4** to generator and mail **Copy 1** to Indiana D.E.M.
OWNER/OPERATOR OUT OF STATE: Retain **Copy 5**, return **Copy 4** to generator and mail **Copy 1** to the TSD State (if applicable) and mail **Copy 3** to Indiana D.E.M.

Indiana generators and TSD facilities must mail the required manifest copies to the State of Indiana within five (5) working days



R00000347
RCRA Records Center

8801 01 932
Hazard Management
Waste Management
IOWA SECTION

SEP 16 1988

USEPA, RCRA Branch

Manifest Tracking Phone Number: (317)243-5014



PLEASE PRINT OR TYPE

(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

**UNIFORM HAZARDOUS
WASTE MANIFEST**

1. Generator's US EPA ID No.

I A D O O O 2 2 2 6 5 3

Manifest
Document No.
M 4

2. Page 1
of 1

Information in the shaded areas is
not required by Federal law, but
items D, F, H and I are required by
State law.

3. Generator's Name and Mailing Address

Climax Molybdenum Co.
Hwy 61 South
Fort Madison, Iowa 52627

4. Generator's Phone (319) 463-7151

5. Transporter 1 Company Name

Heritage Transport

7. Transporter 2 Company Name

6. Use EPA ID Number

I N D O 5 8 4 8 4 1 1 4

8. Use EPA ID Number

.

9. Designated Facility Name and Site Address

Heritage Environmental Services
7901 West Morris St.
Indianapolis, Ind. 46231

10. Use EPA ID Number

I N D O 9 3 2 1 9 0 1 2

A. State Manifest Document Number

INA 0273590

B. State Generator's ID

C. State Transporter's ID

D. Transporter's Phone 317/241-9408

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID

H. Facility's Phone

319/243-0811

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

No.

Type

13.
Total
Quantity

14.
Unit
Wt./Vol.

I.
Waste No.

a.	RQ, Hazardous Waste Solid ORME-E, NA9189, (EPA-EPTTOXI)	1	T T	1.6	T	D004
b.	
c.	
d.	

J. Additional Descriptions for Materials Listed Above

Molybdenum Sulfide Cake, Exempt
from RCRA by paragraph, 261.4

K. Handling Codes for Wastes Listed Above

D004

15. Special Handling Instructions and Additional Information

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Thomas E. Anderson

Signature

Thomas E. Anderson

Month Day Year
09 14 88

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Clyde Bunch

Signature

Clyde Bunch

Month Day Year
09 14 88

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year
. . .

19. Discrepancy Indication Space

RECEIVED

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted Item 19.

Printed/Typed Name

Signature

Month Day Year
. . .

SEP 19 1988
IOWA SECTION

COPY 2. GENERATOR MAIL TO GENERATOR STATE

In case of a spill call the Indiana Office of Environmental Response at 317/241-4336 (day or night) and the National Response Center at 800/424-8802 or 202/426-2675.

INA 0273590

INSTRUCTIONS TO GENERATORS (Please type or print clearly)

- (1) Enter **generator's** U.S. EPA twelve digit identification number and the unique five digit document number assigned to this Manifest (e.g., 00001) by the generator.
- (2) Enter total number of pages comprising this Manifest.
- (3) Enter **generator's** name and mailing address.
- (4) Enter telephone number where an authorized agent of the **generator** may be reached in event of an emergency.
- (5, 6) Enter company name and U.S. EPA I.D. number of the first **transporter** who will transport the waste.
- (7, 8) If applicable, enter company name and U.S. EPA I.D. number of the second **transporter** who will transport the waste. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA Form 8700-22A).
- (9, 10) Enter company name, **site** address, and U.S. EPA I.D. number of the **facility** designated to receive the waste listed on this Manifest.
- (11) Enter U.S. DOT Proper Shipping Name, Hazard Class, and I.D. number (UN/NA) for each waste as identified in 49 CFR 171 through 177. Note: If additional space is needed for waste descriptions, enter in Item 28 on the Continuation Sheet (EPA Form 8700-22A).
- (12) Enter number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I — Types of Containers

DM—Metal drums	TT—Tank Trucks	CM—Metal boxes (including roll-offs)
DW—Wooden drums	TC—Tank cars	CW—Wooden boxes
DF—Fiberboard/plastic	DT—Dump truck	CF—Fiber or plastic boxes
TP—Tanks portable	CY—Cylinders	BA—Bags

- (13) Enter total quantity of waste described on each line.
- (14) Enter appropriate abbreviation from Table II (below) for the unit of measure.

Table II — Units of Measure

P = Pounds	L = Liters (liquids only)
K = Kilograms	G = Gallons (liquids only)
Y = Cubic yards	T = Tons (2,000 lbs.)
N = Cubic meters	M = Metric tons (1,000 kg.)

- (16) The **generator** must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below.

THE FOLLOWING INFORMATION IN THE SHADED AREAS IS REQUIRED BY INDIANA STATE LAW

- (D) Enter the phone number of **first transporter**.
- (F) Enter the phone number of **second transporter** (if applicable).
- (H) Enter the phone number of the designated facility.
- (I) Enter the most appropriate EPA waste code.

GENERATOR IN STATE: Retain **Copy 8** and detach and mail **Copy 2** to Indiana D.E.M.

GENERATOR OUT OF STATE: Retain **Copy 8** and mail **Copy 2** to the Generator State (if applicable) and mail **Copy 3** to Indiana D.E.M.

INSTRUCTIONS TO TRANSPORTERS (Please type or print clearly)

- (17, 18) Enter name of the person accepting the waste on behalf of the **transporter**. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

TRANSPORTER(S): Retain **Copy 7 (Copy 6)** and leave remaining copies with **FACILITY OWNER/OPERATOR**.

INSTRUCTIONS TO OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES (Please type or print clearly)

- (19) The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any discrepancy between the waste described on the Manifest and the waste actually received at the facility.
- (20) Print or type name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

OWNER/OPERATOR IN STATE: Retain **Copy 5**, return **Copy 4** to generator and mail **Copy 1** to Indiana D.E.M.

OWNER/OPERATOR OUT OF STATE: Retain **Copy 5**, return **Copy 4** to generator, mail **Copy 1** to the TSD State (if applicable) and mail **Copy 3** to Indiana D.E.M.

Indiana generators and TSD facilities must mail the required manifest copies to the State of Indiana within five (5) working days of shipment or receipt of the waste (IC 13-7-8.5-7).

Address all manifest copies:

Indiana Department of Environmental Management
Office of Solid and Hazardous Waste Management
P.O. Box 7035
Indianapolis, IN 46207-7035

RECEIVED
SEP 16 1988


USEPA, RCRA Branch

Manifest Tracking Phone Number: (317) 243-5014

CLIMAX MOLYBDENUM COMPANY
AMAX MOLYBDENUM DIVISION

AMAX INC

P. O. BOX 220 • FORT MADISON, IOWA 52627



EPA Region 7
Iowa RCRA
726 Minnesota Avenue
Kansas City, Kansas 66101

